



IFB No. 0823-22-TBCI
Trammel Branch Culvert Improvements Phase 2 Project

Date: August 17, 2022

ADDENDUM #4 (FINAL)

To: **ALL PROSPECTIVE BIDDERS**

THIS ADDENDUM MUST BE SIGNED AND RETURNED WITH YOUR BID.

CLARIFICATIONS & CORRECTIONS

▪ **(REVISE) ATTACHMENT J SPECIAL PROVISIONS – SECTION XIII. UTILITIES:**

If any counterpoise (ground wire buried eighteen (18) to twenty-four (24) inches deep) is damaged, cut or severed, notify Gregory (Greg) Boutchyard, Supv. Transmission Lines; copy Gary Dorman, Sr. Right-of-Way Management Representative with Dominion; and Anthony (Tony) Dudley, Project Manager with the City, immediately so that necessary repairs can be made.

Dominion: Gregory Boutchyard Contact Information

Mobile: (540) 621-0844

E-Mail: gregory.a.boutchyard@dominionenergy.com

Dominion: Gary Dorman Contact Information

Mobile: (703) 999-6522

E-Mail: gary.dorman@dominionenergy.com

City: Antony (Tony) Dudley Contact Information

Mobile: (571) 238-6370

E-Mail: adudley@fallschurchva.gov

▪ **(REPLACE) ATTACHMENT L SUPPLEMENTAL SPECIFICATIONS – SECTION 201 CURED-IN-PLACE PIPE (CIPP) LINING INSPECTION:**

201.03 – Procedures

The City-approved third-party inspections firm shall conduct all required inspections of the CIPP installation and collect all required documentation for inclusion in a report submittal to the City.

Third-party inspector shall be a NASSCO (National Association of Sewer Service Companies) or equivalent Certified CIPP Inspector. The Certified CIPP Inspector shall be onsite while CIPP Operations take place to ensure that CIPP is installed in accordance with specifications included on plans, requirements of Supplemental Specification Section 200, and best management practices. The Contractor shall have an independent CIPP inspector.

Questions and Answers

- Q1. Per Attachment L – Section 201 Cured-In-Place Pipe (CIPP) lining inspection states “Third Party inspector shall be certified by the liner manufacturer”. Subcontractors that will install CIPP Lining are also the manufacturer of the Liner Product. We are having a lot of trouble finding an engineer who will price Third Party CIPP Inspector because of a conflict of interest. Please review or consider removing this item from the Pricing Schedule.
- A1. See above correction for Attachment L *Supplemental Specifications, Section 201 Cured-In-Place Pipe (CIPP) Lining Inspection.*

ATTACHMENTS:

- N/A

ALL OTHER TERMS AND CONDITIONS REMAIN UNCHANGED AND IN FULL FORCE & EFFECT.

Contractor must take due notice and be governed accordingly. This Addendum is considered a part of the above referenced solicitation.

Acknowledged by:

Name of Firm

Authorized Signature

Date